

IN THE UNITED STATES BANKRUPTCY COURT  
FOR THE WESTERN DISTRICT OF PENNSYLVANIA

IN RE:

**ANDREW KOTELES                    ) Bankruptcy No.: 17-23972-JAD**  
**Debtors                         ) Chapter 13**

STEVE LEVANDOSKY and LINDA )  
LEVANDOSKY, his wife, )  
 )  
Movants )

VS. ) No.:

ANDREW KOTELES, )  
)  
)  
Respondent )

VS. )

RONDA J. WINNECOUR, TRUSTEE, )  
)  
Trustee. )

## EXHIBITS and WITNESS LIST

Neil J. Marcus, Esquire  
P.O. Box 652  
Monongahela, PA 15063  
Pa. ID: 23432  
724-258-844  
neiljmarcus@comcast.net

Attorney for Creditors/Petitioners  
Steve and Linda Levandosky



## Site Inspection Report Summary

**Property Address:** 6231 PA-88 Finleyville, PA 15332

**Inspection Date:** 06/10/2020

**Inspector:** Nathan J. Marcus, E.I.T.

*This document is a brief synopsis of the complete seventy page property report.*

### **Narrative of the Site Inspection:**

The Andrew Koteles property inspection was arranged by this inspector, Nathan Marcus, at the request of Steve and Linda Levandosky. I contacted Attorney Justin P. Schantz, Esq. at the law firm of David A. Colecchia and Associates, 324 South Maple Avenue, Greensburg, PA 15601-3219 to make arrangements to inspect the property.

Mr. Koteles was present for the inspection on the date of June 10, 2020.

Mr. Koteles was adamant to not allow Mr. and Mrs. Levandosky to join this inspector on touring the property. This represented a deviation from our initial agreement coordinated with Attorney Schantz. Mr. Levandosky constructed a majority of the structures on the property. With his special historical knowledge, Mr. Levandosky would have been helpful to assist in determining the current condition of the property. Due to Mr. Koteles obstinate refusal to allow Mr. and Mrs. Levandosky to join in the property inspection, I proceeded to inspect the property alone.

My inspection included an investigation and condition assessment of both the land and structural improvements present on the property.

In my professional opinion, the land was in poorly maintained condition. Significant overgrowth of grasses and plants were observed in both the front and rear areas of the property. Large plants were present in the rear area of the property. Several were seen growing through parked automobiles. One plant was growing through the inside of a rear structure (the white building). Detailed observations are noted and documented via photographs in the site report.

All major structures on the property were inspected. The major structures included the front garage bays, rear garage bays, and a white garage / equipment building in the rear.

Overall, Mr. Koteles has neglected taking care of the structural improvements on the property. I saw significant deterioration due to a lack of proper maintenance.

**Site Inspection Methodology:**

The site was inspected starting from the front parking lot near PA SR-88 and proceeding to the rear of the property. The exterior areas of the structures were examined first, followed by the interior areas. Large structural components including roofs, walls, and flooring were examined. Smaller structural elements including electrical, plumbing, heating, and fire protection systems were also examined. No ladders were used to access the roof, attic, or ceiling areas in structures.

**Overall Facility Condition:**

The property improvements feature obvious deferred maintenance and are in need of some significant repairs. The land has obvious deferred maintenance. Multiple building components need repairs, rehabilitation, or updating. The functional utility and overall facility operational capability are diminished due to condition, but the property remains useable and operational as an automotive repair business.

**Detailed Property Description and Significant Deficiencies:**

The property's primary use at the time of inspection was that of an automotive repair business. Commercial signage was clearly visible upon initial access to the property from PA State Road Route 88 as to this property usage.

**Parking Area:**

I observed that the automotive repair facility parking lot was mostly unpaved and lacked a contiguous impervious surface. (Impervious surface being defined as a parking lot constructed of asphalt, concrete, and / or cement). The surface material of the parking lot was primarily gravel. However, the gravel was noted to be thinly distributed throughout the parking lot. Potholes and ruts in the parking lot were clearly visible. The few areas of the parking lot that had impervious surfaces had observable damage due to cracking.

**Roof:**

Overall, the roof is in poor condition. The roof of the structure containing the main garage bays closest to PA SR-88 was observed first. Viewed from the "front-side" of the building, there was visible roof sagging concentrated at a depression in the roof shingles. Viewed from the "rear-side" of the building, there was obvious deterioration in the condition of most of the roof shingles. Damage to the roof flashing was observed along the sides of the building. Wood paneling under the roof structure needs repainted. An unsecured roof downspout was observed during the inspection. Failure to correct the roof will lead to further damage and a diminution in property value.



### **Fire Protection:**

Fire protection of the facility was checked during the site inspection. The fire protection strategy is inadequate.

As an automobile facility, there are inevitably oil spills and oily rags that accumulate during the operation of the business. This creates a higher-than-average flammability risk.

In the front maintenance bays, one small fire extinguisher was found during the course of inspection in an unmarked location on the floor. This area is filled with miscellaneous items not related to fire suppression. Fire extinguishers should be clearly marked and mounted on the wall.

In the rear garage bay storage area, (the rear portion of the main building with the largest garage doors located at the property), a large quantity of rubber tires not on rims were observed to be piled up in the room. No ceiling mounted sprinkler system above the tires or any fire extinguishers were observed in the tire storage room. The tire storage area is in the same overall structure as the front maintenance bays where most customers and customer vehicles are located.

The white building on the portion of the property farthest from PA SR-88 had an observable large burn mark on the ground adjacent to the right exterior area of the structure. Multiple open containers of oil were found inside of the structure. Only one partially charged fire extinguisher, (covered in spider webs with an outdated inspection tag), was found inside of the white building.

### **Exterior Lighting:**

Exterior lighting to illuminate the outside areas of the property at night was unable to be tested to see if it was operational on the day of inspection. Mr. Koteles was asked to operate the exterior lighting. However, he claimed not to know how to turn on the lighting during daylight hours.

### **Garage Service Bays:**

The front service bays have significant wear and tear. The front service bays need maintenance. The brick pillars between the service bay garage doors were damaged. Also, the garage doors had moderate damage and scrapes visible. There are large areas of the ceiling in the main service bays with significant damage. Large holes in the ceiling were observed. Some cracking of the cement floor in the front service bay area was noted. Rear shelving on the walls of the front service bay was crooked. Possibly, the shelving has been overloaded at times to create this condition. Burn and exhaust marks were observed on a wall to the left side of the garage area.

The rear service bays are currently used primarily for tire and miscellaneous junk storage. No fire protection was observed in this area. The flooring of this garage area is an unfinished surface of dirt and gravel. Oil stains were noted on the unfinished surface. The storm doors accessing this structure are in a damaged condition with extensive rust, trim, and lock damage. The large rear garage doors were not tested for operational capability during the inspection.

The rear white building appears to be used for maintenance projects and miscellaneous equipment storage. The steel storm door to access the building has extensive trim rot. The inside of the building has several oil stains noted on the flooring. At the rear of the building under a blue steel wall cabinet, an outside weed plant was observed to be growing through the exterior wall to the inside of the building.

**Steel Access Doors:**

All of the doors for customer and employee access to the building had significant amounts of wear and tear. There are various amounts of visible rust on the steel portions of all the doors. It is recommended to repaint the doors. Multiple doors have striker plate damage. A door to access the rear service bays with tire storage has significant damage to the lower door plate. The white building access door at the far rear of the property has extensive rot around the door trim.

**Electrical:**

In the front service bay area, one area had a large amount of equipment plugged into one electrical circuit.

In the white building at the rear of the property, the light switch closest to the access door to the building was missing a light switch cover.

**Landscaping:**

There was a noticeable amount of high grass and large weeds observable throughout the property.

The rear storage lot has the largest quantity of plant overgrowth. At least one vehicle in the rear lot area was observed to have been parked so long that plants are growing through the vehicle. There are large plants growing adjacent to the rear white building.

The plants near the property utility connections at the main front garage building needs trimmed.


A wasp nest was found adjacent to the inside of the door to access the rear storage area.

**Conclusion:**

Overall, Mr. Koteles has neglected taking care of the structural improvements included on the property. I saw significant deterioration due to a lack of proper maintenance.

*\*These deficiencies and additional property condition information are recorded in the complete seventy page property report.\**

**Inspector: Nathan Marcus, E.I.T**



# Checklist

## Commercial Property Building Inspection Checklist

Koteles / Lendosky Gorge Finleyville

Inspector(s):

*Math  
Mun*


Date:

*6/10/2020*

Location	YES	NO	N/A	COMMENTS
Is the property's address clearly visible from the roadway?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Is the parking lot properly striped?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<i>Gravel, loose</i>
Are there an appropriate number of handicapped spots in the parking lot?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Are there designated spots for hybrids/compact cars?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is there proper lighting in the parking lot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there cracks in the pavement that need to be repaired?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<i>Gravel, but</i>
Are unloading zones clearly marked?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Are there wheelchair-accessible ramps leading up to the main entrance?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Are there handrails leading up to the main entrance?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any obstructions in front of fire hydrants?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Is there a trash dumpster on-site?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Are ash trays available near entrances? Or are no-smoking signs posted?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Are utility/cable boxes properly marked?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<i>OK Cond</i>
Is the property shovelled and/or plowed during the winter?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<i>Summer on 88° day</i>

Building Exterior	YES	NO	N/A	COMMENTS
Are exit doors unlocked during business hours?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<i>Unknown</i>
Are all entrances and exits properly marked?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is the company's name clearly visible?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Is the building's roof in good shape?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are windows and doors in need of a washing?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Is the exterior siding in good shape?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<i>Repoint + Cinder block</i>

This checklist is merely a guideline. It is neither meant to be exhaustive nor meant to be construed as legal advice. It does not address all potential compliance issues with federal, provincial or local standards. Consult your licenced commercial property and casualty representative at Schill Insurance Brokers Ltd or legal counsel to address possible compliance requirements. © 2006, 2012, 2014 Zywave, Inc. All rights reserved.



# Checklist

## Commercial Property Building Inspection Checklist

H/K  
Function OK




Is the building free of vandalism?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are "No Smoking" signs posted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are emergency exits clearly marked and free of obstructions?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Modular
Is there sufficient lighting on the building's exterior?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Unknown if question c /
Is the rooftop elevator penthouse properly ventilated and cleaned regularly?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Are there any cracks in the building's exterior walls?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are combustible materials kept away from the building?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there signs of weather damage?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is the parking structure properly maintained?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are the gutters free of debris?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Uncertain

Landscaping	YES	NO	N/A	COMMENTS
Does the landscaping interfere with any utility boxes?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Modular h of gas
Are there any dead trees on the property?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Are there shade-providing trees on the property?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any areas with dead grass?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Is an irrigation system in place?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Are sprinklers placed far away from walkways?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Are planters properly mulched?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is grass mowed weekly?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are mowers/trimmers kept on-site in a locked storage building?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Are insecticides regularly applied to plants?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are flower beds weeded regularly?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Is grass fertilized regularly?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Electrical Systems	YES	NO	N/A	COMMENTS
Are all electrical boxes, outlets and switches properly covered?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are electrical panels properly covered and latched?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are electrical panels free of obstructions?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are extension cords used for temporary uses only?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Do any extension cords run through walls, ceilings or doors?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Do all electrical outlets have covers?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

This checklist is merely a guideline. It is neither meant to be exhaustive nor meant to be construed as legal advice. It does not address all potential compliance issues with federal, provincial or local standards. Consult your licenced commercial property and casualty representative at Schill Insurance Brokers Ltd or legal counsel to address possible compliance requirements. © 2006, 2012, 2014 Zywave, Inc. All rights reserved.





# Checklist

## Commercial Property Building Inspection Checklist


Is equipment that requires higher voltage plugged into the proper outlets?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Are there any frayed wires in the building?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Do all outlets located within two metres of sinks and exterior doors include Ground-Fault Circuit Interrupters (GFCIs)?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<i>None seen</i>
Is there a lockout procedure in place?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Fire Protection	YES	NO	N/A	COMMENTS
Are there any combustibles stored in the boiler room?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are all smoke alarms functional?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<i>None seen</i>
Are smoke alarms tested regularly?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is smoking prohibited in the building?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the building have a sprinkler system?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is the sprinkler system inspected annually?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is all storage at least 45 cm below the sprinklers?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Are portable fire extinguishers readily available?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are fire extinguishers inspected regularly?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are fire evacuation diagrams posted throughout the building?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there "EXIT" signs posted above exterior doors?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are flammable and combustible liquids properly tagged and stored?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
If smoking is allowed, are smoking areas properly identified?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Heating/Cooling System	YES	NO	N/A	COMMENTS
Is the boiler room kept locked?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Are there any combustible objects kept near heaters?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Is the building's thermostat kept at a comfortable temperature?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Are filters replaced regularly?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Are heating and cooling ducts free of obstructions?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is the heating/cooling system set back when the building is unoccupied?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Housekeeping	YES	NO	N/A	COMMENTS
Is trash removed from the building daily? And from site weekly?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<i>Tuesday pickup</i>

This checklist is merely a guideline. It is neither meant to be exhaustive nor meant to be construed as legal advice. It does not address all potential compliance issues with federal, provincial or local standards. Consult your licenced commercial property and casualty representative at Schill Insurance Brokers Ltd or legal counsel to address possible compliance requirements. © 2006, 2012, 2014 Zywave, Inc. All rights reserved.



# Checklist

## Commercial Property Building Inspection Checklist

Are bathrooms cleaned daily?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Are windows cleaned regularly?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Does the company have a recycling policy?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Are refrigerators emptied and cleaned monthly?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Storage	YES	NO	N/A	COMMENTS
Are all combustible and flammable liquids stored properly?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is there any combustible storage in unprotected attics or crawl spaces?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Did not go in crawl space
Are cabinets and containers containing chemicals properly labelled?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are spill-containment materials readily available in case of a spill?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Cat litter
Are Safety Data Sheets (SDS) available for hazardous substances?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Property address: 6231 PA-88 Finleyville, PA 15332

## **Photo Report of Koteles Garage**

**Site Inspection Date: 06/10/2020**

**Inspector: Nathan Marcus, E.I.T.**

**Prepared for: Levandosky v. Koteles Dispute**




Property address: 6231 PA-88 Finleyville, PA 15332



Sign identifying business on front of lot on PA State Route 88



Property address: 6231 PA-88 Finleyville, PA 15332



Mailbox with street address of property. Mismatched unpainted wood holding it up.

Property address: 6231 PA-88 Finleyville, PA 15332



Overall view of the front of the property. Lot is unpaved. The gravel is thin. Parking spots are unpainted. Exterior lights were not confirmed to be operational during the site visit.




Property address: 6231 PA-88 Finleyville, PA 15332



Roof sagging is visible from the front view of the building's roof shingles.


Property address: 6231 PA-88 Finleyville, PA 15332



Extensive roof shingle wear and tear is evident from a rear view of the building facing towards PA SR-88




Property address: 6231 PA-88 Finleyville, PA 15332



Unrepaired damage at the lower corner of the roof.


Property address: 6231 PA-88 Finleyville, PA 15332



Brown flashing is pulling away from the roof line




Property address: 6231 PA-88 Finleyville, PA 15332



Trim pulling away from the building. External light above the trim was not confirmed to be operational.



Property address: 6231 PA-88 Finleyville, PA 15332



Wide overview of front lot. Note the holes, ruts, and defects in the parking lot.




Property address: 6231 PA-88 Finleyville, PA 15332



Damage to cement pad near front door.



Property address: 6231 PA-88 Finleyville, PA 15332



Cracking pavement near the access transition between SR-88 and Koteles Garage




Property address: 6231 PA-88 Finleyville, PA 15332



Loose pile of gravel near front parking spot. Note how thin the parking lot gravel is.



Property address: 6231 PA-88 Finleyville, PA 15332



Additional cracking in the front parking lot.

Property address: 6231 PA-88 Finleyville, PA 15332



Overall view of front garage bays. Some damage at lower portions of brick pillars can be seen.



Property address: 6231 PA-88 Finleyville, PA 15332



Building damage and cracking between front garage bays.



Property address: 6231 PA-88 Finleyville, PA 15332



Building damage and cracking between front garage bays.



Property address: 6231 PA-88 Finleyville, PA 15332



Building damage and cracking between front garage bays.



Property address: 6231 PA-88 Finleyville, PA 15332



Roof downspout is unsecured from the building. There is wall damage and pavement cracking in front of garage doors.

Property address: 6231 PA-88 Finleyville, PA 15332



Properly secured downspout on rear of building. However, note the uncut grass and weeds near building.



Property address: 6231 PA-88 Finleyville, PA 15332



Extremely rusty rear door in need of paint. Grass needs cut. Additional views of trim pulling away above rear garage doors.


Property address: 6231 PA-88 Finleyville, PA 15332



Wooden roof panels are in need of painting.




Property address: 6231 PA-88 Finleyville, PA 15332



Rusty door. Unpainted trim.

Property address: 6231 PA-88 Finleyville, PA 15332



Rusty door, unpainted trim, plants growing under trim.



Property address: 6231 PA-88 Finleyville, PA 15332



Damaged lower door plate view #1



Property address: 6231 PA-88 Finleyville, PA 15332



Damaged lower door plate view #2




Property address: 6231 PA-88 Finleyville, PA 15332




Door striker plate damage

Property address: 6231 PA-88 Finleyville, PA 15332



Bent / damaged wood around door frame.


Property address: 6231 PA-88 Finleyville, PA 15332



Overgrowth and debris near the white shed on the rear of the property.




Property address: 6231 PA-88 Finleyville, PA 15332



Overgrowth and debris near the white shed on the rear of the property. Notice the rear door condition.

Property address: 6231 PA-88 Finleyville, PA 15332



Rotting wood located around rear wooden door.



Property address: 6231 PA-88 Finleyville, PA 15332



Large burn mark in the ground adjacent to the rear white shed.


Property address: 6231 PA-88 Finleyville, PA 15332



Cracking above the front entry door adjacent to the property's front garage bays.



Property address: 6231 PA-88 Finleyville, PA 15332



Extensive wear and tear on front entry door for customers. Rusty, needs repainted, damaged striker plate.

Property address: 6231 PA-88 Finleyville, PA 15332



Ceiling damage in main bay area.




Property address: 6231 PA-88 Finleyville, PA 15332



Ceiling damage in main bay area.


Property address: 6231 PA-88 Finleyville, PA 15332



Ceiling damage in main bay area.




Property address: 6231 PA-88 Finleyville, PA 15332



Ceiling damage in main bay area.


Property address: 6231 PA-88 Finleyville, PA 15332



Ceiling damage in main bay area.



Property address: 6231 PA-88 Finleyville, PA 15332



Ceiling damage in main bay area.


Property address: 6231 PA-88 Finleyville, PA 15332



Ceiling damage in main bay area.




Property address: 6231 PA-88 Finleyville, PA 15332



Crooked shelving. Previously overloaded?




Property address: 6231 PA-88 Finleyville, PA 15332



Crooked shelving. Previously overloaded?



Property address: 6231 PA-88 Finleyville, PA 15332



Highly loaded single circuit.


Property address: 6231 PA-88 Finleyville, PA 15332



Highly loaded single circuit.



Property address: 6231 PA-88 Finleyville, PA 15332



Burn mark or exhaust located on wall of the main bay.


Property address: 6231 PA-88 Finleyville, PA 15332



Only fire extinguishers found in the main bay placed in misc equipment pile on floor. Extinguishers not clearly marked where located.



Property address: 6231 PA-88 Finleyville, PA 15332



Missing light switch cover in rear white building.


Property address: 6231 PA-88 Finleyville, PA 15332



Missing light switch cover in rear white building. Old partially charged fire extinguisher.




Property address: 6231 PA-88 Finleyville, PA 15332



Old partially charged fire extinguisher. Only fire suppression found in rear white building. Where burn mark was found in ground outside adjacent to the structure.


Property address: 6231 PA-88 Finleyville, PA 15332



Old partially charged fire extinguisher. Only fire suppression found in rear white building. Where burn mark was found in ground outside adjacent to the structure.



Property address: 6231 PA-88 Finleyville, PA 15332



Old partially charged fire extinguisher. Only fire suppression found in rear building.

Property address: 6231 PA-88 Finleyville, PA 15332



Old partially charged fire extinguisher. Only fire suppression found in rear building.



Property address: 6231 PA-88 Finleyville, PA 15332



Oil stain and floor cracking in rear white building.



Property address: 6231 PA-88 Finleyville, PA 15332



Oil spill absorbing material left on the floor in the rear white building.



Property address: 6231 PA-88 Finleyville, PA 15332



Open oil containers and oil spill absorbant material left on the floor.


Property address: 6231 PA-88 Finleyville, PA 15332



Cracking seen in shop floor area.



Property address: 6231 PA-88 Finleyville, PA 15332



Moderate damage to this main bay garage door.

Property address: 6231 PA-88 Finleyville, PA 15332



Dumpster located on the property. Mr. Koteles stated the dumpster is collected every Tuesday.




Property address: 6231 PA-88 Finleyville, PA 15332



Overgrowth and loose pallet near the property's utility connections.



Property address: 6231 PA-88 Finleyville, PA 15332



Overgrowth and weeds on the rear lot.



Property address: 6231 PA-88 Finleyville, PA 15332



Overgrowth and weeds on the rear lot.



Property address: 6231 PA-88 Finleyville, PA 15332



Overgrowth and weeds on the rear lot.




Property address: 6231 PA-88 Finleyville, PA 15332



Overgrowth and weeds on the rear lot.




Property address: 6231 PA-88 Finleyville, PA 15332



Overgrowth and weeds on the rear lot.



Property address: 6231 PA-88 Finleyville, PA 15332



Overgrowth and weeds on the rear lot.



Property address: 6231 PA-88 Finleyville, PA 15332



Debris pile in rear garage




Property address: 6231 PA-88 Finleyville, PA 15332



Oil spill on gravel in rear garage.


Property address: 6231 PA-88 Finleyville, PA 15332



Plant from the outside is growing into the rear storage building.



Property address: 6231 PA-88 Finleyville, PA 15332



Wasp nest near rear entry door.